

RIV Secondary Moisture Trap

NOW AVAILABLE!



Order Part #
432030


Masport[®]

6801 Cornhusker Hwy
Lincoln, NE 68507

Phone (402) 466-8428
Fax (402) 466-8355

www.MasportPump.com

RIV Secondary Moisture Trap Rebuild Kit



Order Part #
432045

Rebuild Kit Includes:

Masport Part No.	Description	Image Item
432041	Spanner Handle for Bowl	6
432042	Bowl - Secondary	3
432043	O - Ring for Bowl	2
432044	Float Ball (Size 60)	4
432046	Rubber Seal	1
432047	Ball Valve Seal	5